

PROGRESS UPDATE April 2023

Southeast Pre K-12 School















Site Development & Landscaping

April 2023 Progress

- Site
- Utilities
 - Continue Site Lighting Conduit- 75%
 - Underground Power Conduit- 75%
 - Underground Data Conduit 90%
 - Light Pole Bases Installation—80%
 - Water Line Installation— 30%
 - Underground Plumbing Installation—100%
 - Below Grade CMU at Pumphouse-100%

- Continue Installing Water Line
- Begin Installing Pumphouse Water Lines
- Continue Installing Underground Power Conduit










Area A


April 2023 Progress

- Second Floor Bearing CMU— 80%
- First Floor MEP Overhead Ongoing-80%
- Interior Metal Framing- 65%
- Exterior Wood Blocking Ongoing- 50%
- Set Hollow Metal Frames 30%

- Second Floor CMU Bearing
- Setting Hollow Metal Frames
- Interior Metal Framing
- Exterior Wood Blocking
- First Floor MEP Overhead Rough-in














Area B

April 2023 Progress

- Foundations 95%
- Below Grade CMU

 80%
- Branch Conduit 50%
- Pour Partial Slab on Grade 10%

- Continue Bearing CMU
- Branch Conduit
- Continue Slab on Grade












Area C

April 2023 Progress

- Second Floor CMU Bearing-55%
- First Floor MEP Overhead Ongoing 80%
- Interior Metal Framing- 70%



- Second Floor CMU Bearing
- First Floor MEP Overhead Rough-in
- Interior Metal Framing










Area D

April 2023 Progress

- Exterior Bearing CMU 30%
- Set Hollow Metal Frames 80%



- Exterior Bearing CMU
- MEP Rough In












Area E

April 2023 Progress

- CMU to Bearing- 60%
- Set Music Room Precast Planks
 100%

Upcoming Progress

Continue CMU to Bearing














Area F

April 2023 Progress

• Exterior Bearing CMU - 75%

Upcoming Progress

Continue Bearing CMU













Area G

April 2023 Progress

• First Floor Bearing CMU- 10%

- First Floor CMU Bearing
- MEP Rough In

